

ENDURA

***Punish Your Screens
- Not Your Bottom Line!***

CASE STUDIES:

ROSEBERY ZINC TASMANIA SCREEN DECK

AR450 80mm = 1.25 Years in Service **ENDURA 80mm = 5 Years and still in service**



+ eliminated cracking + spot welding repair

**400%
SERVICE
LIFE
IMPROVEMENT**

HARRISBURG, PA – SHINGLE RECYCLING MOBILE CRUSHER

AR500 1" Screen = 20 Days **ENDURA 1" Screen = 55 days**



**275%
SERVICE
LIFE
IMPROVEMENT**


RIO TINTO IRON ORE MINE, PILBARA GRIZZLY DECK FINGERS FOR ORE SEPERATION

AR500 = 9 Months in Service **ENDURA = 24 Months in Service**



**250%
SERVICE
LIFE
IMPROVEMENT**

TITUS
STEEL



ENDURA


For Operations

With No Time for Down Time!

CASE STUDIES:

TIRE RECYCLING : BAYLOR COUNTY, TX

AR500 3/8" = 4.5 months in service **ENDURA 3/8"** = 10 + months in service



**225%
SERVICE
LIFE
IMPROVEMENT**

HAMILTON, ON - DOFASCO STEEL MILL - STEEL SLAG SCREEN DECK

Steel Slag Screen Deck **AR400** = 12 Months **ENDURA** = 42 Months (3.5 years)



**350%
SERVICE
LIFE
IMPROVEMENT**



sales@titussteel.com

+1 888 564 7904 | +1 905 564 2446

TITUS STEEL COMPANY LIMITED

Wear Steels - Engineering Products & Design

www.titussteel.com