


ENDURA Wear Solutions

ENDURA 80mm Grizzle Decks handle Hard Rock Impact Abrasion

Case Study 2010 - 2016



ENDURA 50mm thick grizzle wear bars caps replace traditional 450 HB wear material and extend service life in Kalgoorlie Gold Mine by over 200%



ENDURA 80 mm thick grizzle replaced previous 450 HB wear plate increasing service life by 400%

The original Rosebery Zinc Tasmania Grizzle manufactured from 450 HB wear plate suffered from high wear rates and fatigue cracking . Routine weld repairs required to maintain the 450Hb grizzle deck in operation .

The current ENDURA 80 mm grizzle decks have been in service for over 5 years with minimal wear and no fatigue crack issue .